Section 7 Modifications Requested with Renewal



Mason, MI · Lakeville, MN · Cincinnati, OH · Spartanburg, SC

USA LAMP & BALLAST RECYCLING, INC

7806 Anthony Wayne Avenue, Cincinnati, OH 45216 513.641.4155 phone / 513.641.4156 fax usalamp@usalamp.com email www.usalamp.com

March 11, 2017

Director Scott J. Nally
Ohio Environmental Protection Agency

Attn: Mr. Jeremy Carroll, Manager Division of Materials and Waste Management Engineering, Remediation, and Authorizing Section Lazarus Government Center 50 West Town Street, Suite 700 Columbus, OH 43215

RE:

USA Lamp & Ballast Recycling, Inc (OHR-000-109-819)
Class 1 Modification Associated with Permit Renewal

Dear Mr. Carroll,

USA Lamp & Ballast Recycling, Inc (OHR-000-109-819) is submitting the enclosed Class 1 modification in conjunction with our Part B Hazardous Waste Permit Renewal

Enclosed you will find the following updated pages:

- RCRA Subtitle C Site Identification update, Pages 48 50
- Hazardous Waste Permit Information Form update, Pages 8 14
- Section B Facility Description B-1, contacts, page 52
- Emergency Response Contingency Plan, Attachment 2, Page 133
- Emergency Response Contingency Plan, Attachment 7, Page 138
- Emergency Response Contingency Plan, Attachment 8, Page 139
- Closure Plan, Section 1, Closure Cost, Page 165
- · Closure Plan, Trust Agreement, Page 167
- Closure Plan, Certificate of Insurance, Page 179

Please do not hesitate to contact me or David Dempsey (864.316.4462 / david.dempsey@usalamp.com) with any questions or comments.

"I certify under penalty of law that this document and all attachments were prepared under my supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Respectfully submitted,

Thomas M Kimmel
President
517.676.0044 phone
usalamp@usalamp.com email

Cc:

Ms. Cathy Altman, DMWM – Southwest District Office

Enclosures:

-	MAIL THE COMPLETED FORM TO: Ohio EPA, DMWM, P.O. Box 1049, Columbus, OH 43216-1049	Onlo Li	ovironmental F BTITLE C SIT					For Ohio EPA Use Only
1.	Reason for Submittal	Reason for Submittal: To provide initial no activities). To provide subsequ As a component of a subseque As a component of a subseque As a component of a subseque As a component of a subsequent As a component of the subsequent A	ent notification (to up a First RCRA Hazard a Revised RCRA Haz	date site ous Was zardous '	e identifica ste Part A Waste Pa	ation informa Permit Appli art A Permit A	tion), cation.	,
2.	Site EPA ID No.	EPA ID Number: OHR-000-109-819						
3.	Site Name	Name: USA Lamp & Ballast Red	cycling, Inc.					
4.	Site Location Information	Street Address: 7806 Anthony Wayne Av City, Town, or Village: Cincinnati State: OH	renue Country US	75		County: Hamiltor	Zip Code: 45216	
5.	Site Land Type	Site Land Type: X Private		ctFe	ederal	Indian		State Other
6.	North American Industry Class. System (NAICS) Code(s) for the Site	A. (Primary) 56200 C.			в. 33511 D.			
7.	Site Contact Person:	First Name: Benny Title: EHS Manager Street or P.O. Box: 7806 Anthony Wayne Av City, Town or Village: Cincinnati State: OH E-mail: benny.coyt@cleanlites.co Phone & Ext.: 513-766-0318	Country: US		MI:	Last Name Coyt	Zip Code: 45216 Fax: 513.641.4	.156
8.	Legal Owner and Operator of the Site	A. Name of Site's Legal Owner: USA Lamp & Ballast Rec				O	Date Became 0 / 6/30/2004	Owner (mm/dd/yyyy): /
		Owner Type Private X C Street or P.O. Box:	ounty District _	Feder	al Llind	dian LIMur	icipal LIStat	e L Other
	Additional Owners and/or Operators	7806 Anthony Wayne Ave City, Town, or Village: Cincnnati					Phone: 513.641.41	55
	should be listed in the	State: OH B. Name of	Country: US			Tr	Zip Code: 45216	Operator (mm/dd/yyyy):
	Comment Section or on another copy	B. Name of Site's Operator: USA Lamp & Ballast Recy Operator Type: X Private		☐ Fed	eral 🔲 I	0	6/30/2002 unicipal St	1
	of this form page.	Street or P.O. Box: 7806 Anthony Wayne Ave	nue					
	-	City, Town, or Village: Cincinnati	16				Phone: 513.641.41 Zip Code:	55
	1	State: OH	Country:				45216	

9. Type of Regulated Waste Activity (Mark "X" in the appropriate boxes.)	
A. Hazardous Waste Activities	For Items 3 through 7, check all that apply:
Generator of Hazardous Waste (choose only one of the following three categories or leave blank if not applicable)	 3. Transporter of Hazardous Waste a. Transporter b. Transfer Facility (at your site)
a. Large Quantity Generator (LQG): Greater than 1,000 kg/mo (2,200 lbs.) of non-acute hazardous waste; or	Treater, Storer or Disposer of Hazardous Waste (at your site) Note: A hazardous waste permit is required for this activity.
b. Small Quantity Generator (SQG) 100 to 1,000 kg/mo (220-2,200 lbs.) of non-acute hazardous waste; or	5. Recycler of Hazardous Waste (at your site) Note: A hazardous waste permit may be required for this activity.
C. Conditionally Exempt Small Quantity Generator (CESQG): Less than 100 kg/mo of non-acute hazardous waste	a. 72-hour Recycler
In addition, indicate other generator activities (check all that apply)	6. Exempt Boiler and/or Industrial Furnace a. Small Quantity On-site Burner Exemption b. Smelting, Melting and Refining Furnace
d. Short-Term Generator (generate from a short-term or one-time event and not from on-going processes). If "Yes", provide an explanation in the Comments section.	Exemption 7. Underground Injection Control
 e. United States Importer of Hazardous Waste f. Mixed Waste (hazardous and radioactive) Generator 	X 8. Receives Hazardous Waste from Off-site
 Hazardous Waste Report Generator Status (choose one if a Reason for Submittal is the Hazardous Waste Report) 	
 a. Large Quantity Generator (LQG): Greater than 1,000 kg/mo (2,200 lbs.) of non-acute hazardous waste was generated at the site in any one month. or 	
b. Small Quantity Generator (SQG) In one or more months the site generated greater than 100kg (220 lbs) but in no month did it generate more than 1,000 kg/mo (220-2,200 lbs) of non-acute hazardous waste, or	
 c. Conditionally Exempt Small Quantity Generator (CESQG): The site generated no more than 100 kg (220 lbs) of non-acute hazardous waste in any one month. 	
 d. Non-Generator The site did not generate any hazardous waste during the calendar year. 	
B. Universal Waste Activities 1. Large Quantity Handler of Universal Waste (accumulate 5,000 kg or more). Indicate types of universal waste managed at your site. (check all boxes that apply):	C. Used Oil Activities 1. Used Oil Transporter Indicate Type(s) of Activity(ies) a. Transporter b. Transfer Facility (at your site)
a. Batteries b. Pesticides c. Mercury Containing Equipment d. Lamps	2. Used Oil Processor and/or Re-refiner Indicate Type(s) of Activity(ies) a. Processor b. Re-refiner
Destination Facility for Universal Waste Note: A hazardous waste permit may be required for this activity.	 3. Off-Specification Used Oil Burner 4. Used Oil Fuel Marketer - Indicate Type(s) of Activity(ies) a. Marketer Who Directs Shipment of Off-Specification Used Oil to Off-Specification Used Oil Burner b. Marketer Who First Claims the Used Oil Meets the Specifications

ł						
D. Eligible Aca	ademic Entities with L OAC rules 3745-52-2	aboratories – Notific 00 through 3745-52-	ation for opting 216	g into or withdrawing	from managing lab	oratory hazardous wastes
1. Opting laborate	into or currently operati ories. Mark all that ap	ng under OAC rules 3 ply:	3745-52-200 thro	ough 3745-52-216 for	the management of h	azardous wastes in
a.	College or University					
b.	Teaching hospital tha	t is owned by or has a	formal written a	affiliation agreement w	ith a college or univer	sity
c.	Non-profit Institute that	at is owned by or has	a formal written	affiliation agreement v	vith a college or unive	rsity
2. Withdra	wing from OAC rules 3	745-52-200 through 3	745-53-216 for t	he management of ha	zardous waste in labo	pratories
10. Waste Code site. List the needed.	es for Federally Regular m in the order they are	ated Hazardous Was presented in the regu	tes. Please list lations (e.g., D0	the codes for the fede 01, D003, F007, U112	rally regulated hazard). Use an additional p	dous waste handled at your page if more space is
D001	D002	D003	D004	D005	D006	D007
D008	D009	D010	D011	D051		
11. Comments	Maryan - Caranta					
USA Lamp & B	allast Recycling, Ir	nc. is a destination	n facility for U	Iniversal Waste la	mps, mercury	
containing item	s, electronic waste	, and batteries. L	.amps are cru	ushed and separa	ted by material ty	ре
then recycled th	nrough other faciliti	es. Electronic wa	astes are diss	embled and recy	cled to other	
facilities. Mercu	ury from the lamp p	process and all ot	her mercury (containing materia	als is recycled at	
the facility. All r	residuals and debr	is from the mercu	ry recycling p	orocess is recycle	d through other	
facilities.						
accordance v on my inquiry the information significant pe	with a system designe y of the person or person on submitted is, to the enalties for submitting	d to assure that qua sons who manage the best of my knowled false information, in	lified personne ne system, or th dge and belief, t ncluding the po	I properly gather and nose persons directly true, accurate, and cossibility of fine and	d evaluate the inform responsible for gat omplete. I am award imprisonment for kn	owing violations.
	owner, operator, or ar ed representative	n Name ar	nd Official Title	(type or print)		e Signed ı-dd-yyyy)
		Thomas M.	. Kimmel, Pre	esident & CEO		
						-
	······································					· · · · · · · · · · · · · · · · · · ·

1	H	łA:	ZA	RI												ion Ager	TION FORM
Facility Permit Contact		Firs	t Na	ıme	:Tin	noth	ıy					M	II: M		_ast	Name: Kir	mmel
Contact		Con	taci	t Tit	le:V	PS	ale	s &	Maı	rket	ing						
	l	Pho	ne:	513	.64	1.41	55							Ext.:			Email: timothy.kimmel@usalamp.com
2. Facility Permit Contact Mailing		Stre	et o	rP.	O. E	Box:	780)6 A	nth	ony	Wa	ayne	e Av	enue	·		
Address	-	City	, To	wn,	or \	/illa	ge:	Cin	<u>cinn</u>	ati		····					
		State	e :0	e:OH													
		Cou	ntry	r: US	SA					~~~			_			Zip Cod	le: 45216
3. Operator Mailing Address and	5	Stre	et o	rP.	O. E	ox:	780)6 A	nth	ony	Wa	ayne	Av	enue	!		
Telephone Number	C	City,	, To	wn,	or \	/illa	ge:	Xin	cinn	ati							
	5	State	e: O	Н											:	Phone:	513.641.4155
	(Cou	ntry	: US	SA_				***********							Zip Cod	e: 45216
4. Facility Existence Date	F	aci	lity	Exis	sten	ce [Date	(m	m/d	d/yy	уу)	:06/	30/	2002			
5. Other Environmenta	al Pe	ermi	its														
A. Facility Type (Enter code)					В.	Per	mit	Nun	nbei	r							C. Description
E	Р	0	1	0	8	5	6	7						PTI	& P7	ΓΟ Fluore	escent Lamp Processor
															•		
											-						
	COH	tall	mıy	ILEI	115,	GIG	Juo	HIC	was	ι c ,	and	Dai	men.	55. L	.am	os are cru	niversal Waste lamps, mercury ushed and separated by material type,
																	assembled and recycled to other at this facility. All residuals and debris
		cilities. Mercury from mercury containing materials is recycled at this facility. All residuals and debris om the mercury recycle process are recycled through other facilities.															

EPA ID Number

7. Process Codes and Design Capacities - Enter information in the Section on Form Page 3

- A. PROCESS CODE Enter the code from the list of process codes below that best describes each process to be used at the facility. If more lines are needed, attach a separate sheet of paper with the additional information. For "other" processes (i.e., D99, S99, T04 and X99), describe the process (including its design capacity) in the space provided in Item 8.
- ... PROCESS DESIGN CAPACITY For each code entered in Item 7.A; enter the capacity of the process.
 - 1. <u>AMOUNT</u> Enter the amount. In a case where design capacity is not applicable (such as in a closure/post-closure or enforcement action) enter the total amount of waste for that process.
 - 2. <u>UNIT OF MEASURE</u> For each amount entered in Item 7.B(1), enter the code in Item 7.B(2) from the list of unit of measure codes below that describes the unit of measure used. Select only from the units of measure in this list.
- C. PROCESS TOTAL NUMBER OF UNITS Enter the total number of units for each corresponding process code.

Process Code	Process	Proce	ate Unit of Measure for ss Design Capacity	Process Code	Proce		Proces	ate Unit of Measure for ss Design Capacity
	Dis	posal		Tr	eatment (Contin	ued)		for T81 – T94)
D79	Underground Injection Well Disposal	Liters Per I	•	T81	Cement Kiln		Per Hour; Sho	Pay; Liters Per Day; Pounds ort Tons Per Hour; r Hour; Metric Tons Per
D80	Landfill		Hectares-meter; Acres; ers; Hectares; Cubic	T82	Lime Kiln		Day; Metric To Per Day; BTU	ons Per Hour; Short Tons Per Hour; Liters Per Hour;
D81	Land Treatment	Acres or H	ectares	T83	Aggregate Kiln			Hour; or Million BTU Per
D82	Ocean Disposal	Gallons Pe	r Day or Liters Per Day	T84	Phosphate Kiln		Hour	
D83	Surface Impoundment Disposal		ters; Cubic Meters; or	T85	Coke Oven			
D99	Other Disposal	Any Unit of	Measure Listed Below	T86	Blast Furnace			
	Sto	rage		T87	Smelting, Meltir	ng, or Refining	g Furnace	
S01	Container	Cubic Yard		T88	Titanium Dioxid	e Chloride Ox	idation Reactor	-
S02	Tank Storage	Gallons; Lit Cubic Yard	ers; Cubic Meters; or s	T89	Methane Reform	ning Furnace		
S03	Waste Pile		s or Cubic Meters	T90	Pulping Liquor I	Recovery Furr	nace	
S04	Surface Impoundment	Cubic Yard	_	T91	Combustion De Sulfuric Acid	vice Used in t	he Recovery of	Sulfur Values from Spent
S05	Drip Pad	Hectares; c	ers; Cubic Meters; or Cubic Yards	T92	Halogen Acid F	urnaces		
	Containment Building Storage	Cubic Yard	s or Cubic Meters	T93	Other Industrial	Furnaces Lis	ted in 40 CFR 2	260.10
S99	Other Storage	Any Unit of	Measure Listed Below	T94	Containment Bu	uilding	Per Hour; Gal	Cubic Meters; Short Tons fons Per Hour; Liters Per
	Trea	tment	W					r Hour; Pounds Per Hour;
T01 T02	Tank Treatment Surface Impoundment		r Day; Liters Per Day r Day; Liters Per Day				Hour; Metric T Day; Liters Pe	er Day; Kilograms Per Tons Per Day; Gallons Per Tor Day; Metric Tons Per In BTU Per Hour
						Miscellaneou	us (Subpart X)	II D I U Pel Hour
T03	Incinerator		Per Hour; Metric Tons					
		Per Hour; E	Gallons Per Hour; Liters GTUs Per Hour; Pounds Ghort Tons Per Day;	X01	Open Burning/C Detonation)pen	Any Unit of Me	easure Listed Below
			Per Hour; Gallons Per Tons Per Hour; or Per Hour	X02	Mechanical Pro	cessing	Hour; Short To Per Day; Pour	er Hour; Metric Tons Per ons Per Day; Metric Tons nds Per Day; Kilograms
T04	Other Treatment	Pounds Per	Day; Liters Per Day; Hour; Short Tons Per rams Per Hour; Metric				Hour; or Gallo	ons Per Hour; Liters Per ns Per Day
		Tons Per D BTUs Per H	ams Per Hour, Metho ay; Short Tons Per Day; lour; Gallons Per Day; lour; or Million BTU Per	X03	Thermal Unit		Per Hour; Sho Kilograms Per Day; Metric To Per Day; BTU	ay; Liters Per Day; Pounds rt Tons Per Hour; Hour; Metric Tons Per ons Per Hour; Short Tons Per Hour; or Million BTU
T80	Boiler	Liters Per H	ers; Gallons Per Hour; lour; BTUs Per Hour; or	X04	Geologic Repos	itory		Cubic Meters; Acre-feet;
		Million BTU	Per Hour	X99	Other Subpart X			; Gallons; or Liters easure Listed Below
Unit of Mea	asure Unit of Mea	asure Code	Unit of Measure		Measure Code	Unit of Mea	· · · · · · · · · · · · · · · · · · ·	Unit of Measure Code
	asure Unit of wee		Short Tons Per Hour				S	Y
Gallons Pe	er Hour	E	Short Tons Per Day		N			C
	er Day		Metric Tons Per Hour.					B
	·····		Metric Tons Per Day					A
	Hour		Pounds Per Hour					Q
Liters Fef	Day	v	Kilograms Per Hour Million BTU Per Hour					F
					**********			· · · · · · · · · · · · · · · · · · ·

.. Process Codes and Design Capacities (Continued)

Li	ne	A	Proc. Code		B. PROCESS DESIGN CAPA	CITY	C. Process Total		=a- A	fficia	l Use	Only	
Nur	nber	(Fro	m list a		(1) Amount (Specify)	(2) Unit of Measure	Number of Units		0, 0	IIICIA	i use	Omy	
Х	1	s	0	2	533.788	G	001						
	1	S	0	1	150	Υ	001						
	2												
	3				For purposes of compliance units are								
	4				equivalent to 325,000 pounds								
	5												
	6												
	7												
	8												Ý.
	9							N.					
	0												
l	1												
	2												
1	3												

ce: If you need to list more than 13 process codes, attach an additional sheet(s) with the information in the same format as above. Number the line sequentially, taking into account any lines that will be used for "other" process (i.e., D99, S99, T04, and X99) in Item 8.

8. Other Processes (Follow instructions from Item 7 for D99, S99, T04, and X99 process codes)

Li Nur	ne nber				B. PROCESS DESIGN CAPACITY								
(Ente	r #s in ience tem 7)	(Froi	rocess m list a	Code bove)	(1) Amount (Specify)	(2) Unit of Measure	C. Process Total Number of Units		For O	fficia	l Use	Only	
Х	2	Т	0	4	100.00	U	001						
					N/A								
													iller in Na Sa
_													
								Mili			100		

- 9. Description of Hazardous Wastes Enter Information in the Sections on Form Page 5
 - 1. EPA HAZARDOUS WASTE NUMBER Enter the four-digit number from 40 CFR, Part 261 Subpart D of each listed hazardous waste you will handle. For hazardous wastes which are not listed in 40 CFR, Part 261 Subpart D, enter the four-digit number(s) from 40 CFR Part 261, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
 - B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in Item 9.A, estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in Item 9.A, estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
 - C. UNIT OF MEASURE For each quantity entered in Item 9.B, enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	Р	KILOGRAMS	К
TONS	Т	METRIC TONS	М

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure, taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:

For listed hazardous waste: For each listed hazardous waste entered in Item 9.A, select the code(s) from the list of process codes contained in Items 7.A and 8.A on page 3 to indicate all the processes that will be used to store, treat, and/or dispose of all listed hazardous wastes.

For non-listed waste: For each characteristic or toxic contaminant entered in Item 9.A, select the code(s) from the list of process codes contained in Items 7.A and 8.A on page 3 to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

NOTE: THREE SPACES ARE PROVIDED FOR ENTERING PROCESS CODES. IF MORE ARE NEEDED:

- 1. Enter the first two as described above.
- 2. Enter "000" in the extreme right box of Item 9.D(1).
- 3. Use additional sheet, enter line number from previous sheet, and enter additional code(s) in Item 9.E.
- 2. PROCESS DESCRIPTION: If code is not listed for a process that will be used, describe the process in Item 9.D(2) or in Item 9.E(2).

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER – Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- Select one of the EPA Hazardous Waste Numbers and enter it in Item 9.A. On the same line complete Items 9.B, 9.C, and 9.D by estimating the total annual quantity of the waste and describing all the processes to be used to store, treat, and/or dispose of the waste.
- 2. In Item 9.A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In Item 9.D.2 on that line enter "included with above" and make no other entries on that line.
- 3. Repeat step 2 for each EPA Hazardous Waste Number that can be used to describe the hazardous waste.

EXAMPLE FOR COMPLETING Item 9 (shown in line numbers X-1, X-2, X-3, and X-4 below) – A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operations. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

Li	ne	A.	EPA I		lous	B. Estimated Annual	C. Unit of Measure							D.	PRO	CESS	BES
Nun	nber		(Enter			Qty of Waste	(Enter code)		(1) P	ROC	ESS (CODE	S (E	nter C	ode)		(2) PROCESS DESCRIPTION (If code is not entered in 9.D(1))
Х	1	K	0	5	4	900	Р	Т	0	3	D	8	0				
Х	2	D	0	0	2	400	Р	Т	0	3	D	8	0				
٧	3	D	0	0	1	100	Р	Т	0	3	D	8	0				
	4	D	0	0	2												Included With Above

		A.		lazard		B. Estimated Annual	C. Unit of	D. PROC							CESS	BES	
Line i	Number	(te No. code)		Qty of Waste	Measure (Enter code)		(1) P	ROC	ESS	CODE	ES (E	nter C	ode)		(2) PROCESS DESCRIPTION (If code is not entered in 9.D(
	1	D	0	0	8	14,714	Т	S	0	1							
	2	D	0	0	6												Included with above
	3	D	0	0	9												Included with above
	4	D	0	1	1												Included with above
	5	D	0	0	1												Included with above
	6	D	0	0	2												Included with above
	7	D	0	0	3												Included with above
	8	D	0	0	4												Included with above
	9	D	0	0	5												Included with above
1	0	D	0	0	7												Included with above
1	1	D	0	1	0												Included with above
1	2	U	1	5	1												Included with above
1	3																
1	4																
1	5																
4	6																
	7																
1	8															<u> </u>	
1	9																
2	0																
2	1																
2	2																
2	3																
2	4																
2	5																
2	6						-										
2	7																
2	8																
2	9																
3	0																
3	1																
3	2																
3	3																
3	4																
	5																
3	6																

-		. EPA	Hazar	dous	B. Estimated Annual	C. Unit of	D. PRO						PRO	CESS	BES	
ine Numbei			ste No r code		Qty of Waste	Measure (Enter code)		(1) F	ROC	ESS	CODI	ES (E	nter C	ode)	ı	(2) PROCESS DESCRIPTIO (If code is not entered in 9.D
	ļ							ļ	ļ	ļ		ļ				
	<u> </u>												ļ		ļ	
				ļ								ļ			ļ	
	ļ															
										-						
							1									
																
			1				 						<u> </u>			
+		1										ļ				
							-	<u> </u>								
		-														
		1	 		***************************************		-									
		-			-		-									
		+					-									
		-					-					ļ				
		-					<u> </u>	ļ								
		-	ļ													
		-				***************************************	ļ									
			ļ													
							ļ									
						······································										
		1														
		1					 									

USA Lamp & Ballast Recycling, Inc - Part B Application Section B Facility Description

The facility consists of two connected structures of approximately 18,133 square feet on approximately 1.00 acre of land located in a ML (Manufacturing Limited) zone.

The contacts and responsible parties for this facility are as follows:

Timothy M. Kimmel
VP, Facility Manager
513.641.4155 / timothy.kimmel@usalamp.com

Benny Coyt
EHS Manager
513.766.0318 / benny.coyt@cleanlites.com

Kyle Amann
Operations Manager
513.641.4155 / usalamp@usalamp.com email

B-2a: <u>TRAFFIC INFORMATION</u> OAC 3745-50-44 (A)(10)

B-2a (1) Traffic patterns on-site:

Figure B-1 in this section shows movement of Waste Material to the facility from the nearest major highway and the traffic control signals encountered along the route. Figure B-2 shows an overview of the facility location.

Access from Interstate 75 at Exit 9 OH-4 / Paddock Road / Seymour Avenue, turn North (Left if coming from the South or Right if coming from the North) onto Paddock Road. Proceed approximately .4 miles to Anthony Wayne Avenue. Bear Right onto Anthony Wayne Avenue; facility entrance is at 7806 Anthony Wayne Avenue on the east side of the road; approximately .3 miles from the intersection of Paddock Road and Anthony Wayne Avenue.

B-2a (2) Estimated volume (e.g. number and types of vehicles):

The estimated volume of universal waste traffic for the USA Lamp & Ballast Recycling facility is as follows: Straight trucks (Van) entering and leaving the facility two (2) to three (3) times daily. Tractor trailers entering and leaving the facility two (2) to three (3) times daily.

ATTACHMENT 2

USA LAMP & BALLAST RECYCLING, INC Emergency Response Contingency Plan

Emergency Response Coordinators

EMERGENCY COORDINATOR

TELPHONE NUMBERS

PRIMARY

Benny Coyt

non-responsive

Business:

Residence: Mobile: (513)766-0318

non-responsive non-responsive

SECONDARY

Timothy M Kimmel

non-responsive

Business:

(513)641-4155

Residence:

on-responsive

Mobile: non-resp

Kvle Amann

1011-responsi

Business: Residence: Mobile: (513)641-4155

non-responsive

ATTACHMENT 7 USA LAMP & BALLAST RECYCLING, INC Emergency Response Contingency Plan

DISTRIBUTION LIST

PERSONNEL

TITLE

Thomas M Kimmel

President and CEO

Timothy M Kimmel

VP, Facility Manager

Michael T Kimmel

Senior VP, Safety & Compliance Officer

Benny Coyt

EHS Manager

Kyle Amann

Operations Manager

Mark Amann

Driver

Ewan Blair

Retort Manager

Michael Diaz Disdier

Recycling Technician

Krista Duskin

Office Assistant

Larry Hizer

Driver

Brady Hobbs

Recycling Technician

Antony Montanez

Recycling Technician | Retort

Jaime Nieves

Recycling Technician

Donna Pechiney

Logistics Coordinator

Luiz Rios-Victor

Recycling Technician

Roberto Rivera Gonzalez

Recycling Technician

Jesus Velez Rosado

Recycling Technician

Luetta Wilson

Office Manager

Jahde Wright

Recycling Technician

Montsho Wright

Recycling Technician

EMERGENCY

TITLE

Hospital

Good Samaritan Hospital

Fire / Environmental & Safety

Services

Cincinnati Fire Department

Police Dept

Police Department, Cincinnati

OH EPA

Emergency Response

7806 Anthony Wayne Avenue Cincinnati, OH 45216 513.641.4155 phone / 513.641.4156 fax usalamp@usalamp.com email

Lt Rick Jones Cincinnati Fire Department 700 W Pete Rose Way Lobby B, 5th Floor Cincinnati, OH 45203

Dear Lt Jones:

USA Lamp & Ballast Recycling, Inc is a local Universal Waste facility that collects, sorts, disassembles and repackages lamps, batteries, lighting ballast, mercury-containing devices and computer / electronic equipment to be sent to the final destination facilities. As part of these operations, USA Lamp & Ballast Recycling generates and manages universal/hazardous waste. USA Lamp & Ballast Recycling, Inc requests your agreement to respond to emergencies at our facility, as appropriate for your function, upon request by USA Lamp & Ballast Recycling Facility personnel.

Enclosed for your information is a copy of the USA Lamp & Ballast Recycling Contingency Plan which can be used to familiarize your emergency response personnel with the layout of the facility, properties of the hazardous wastes handled at the facility and associated hazards, places where facility personnel would normally be working, entrances to the facility and possible evacuation routes.

Please respond to this request in writing. A self-addressed return envelope is enclosed for your use.

If you should have any questions, please contact me at 513.641.4155 or benny.coyt@cleanlites.com.com.

Respectfully submitted,

Benny Coyt Primary Emergency Coordinator USA Lamp & Ballast Recycling, Inc

USA Lamp & Ballast Recycling, Inc Conting	gency Plan Receipt and Acknowledgement
Print / Type Name and Title	
Signature	Date

USA Lamp & Ballast Recycling, Inc - Part B Application Section I CLOSURE PLAN Attachment A CLOSURE COSTS

ESTIMATED CLOSURE COSTS 03/2017 Renewal

1.	Processing of remaining lamp inventory 175,000 pounds of unprocessed lamps @ \$0.06 / lb	\$10,500.00
2.	Transportation of remaining lamp inventory to third party facility	\$1,200.00
3.	Retort mercury containing debris / residuals (includes dry residue from clean-up prod (200 drums at \$240.50 per drum)	
4.	Transportation of mercury containing debris / residuals and 2 drums clean-up material by hazardous waste carrier	\$1,200.00
5.	Disassemble processing equipment; decontaminate and load for transport for sto (16 hours at \$62.50/hour)	
6.	Decontaminate facility floors, walls and ceilings (16 hours at \$62.50 per hour)	\$1,000.00
7.	Collect wipe samples from floors, walls and ceilings	\$300.00
8.	Lab analysis of wipe samples (15 samples @ \$53.33/analysis)	\$800.00
9.	Complete additional facility or equipment decontamination as required by test res (8 hours at \$62.50 per hour)	sults. \$500.00
10.	Collect additional wipe samples from within facility surfaces (if necessary)	\$300.00
11.	Lab analysis of additional wipe samples (if necessary) (15 samples @ \$53.33/analysis)	\$800.00
12.	Disposal of two (2) drums of hazardous waste clean-up material (The majority of clean-up material will be dry residue from the vacuuming process and wi with the material sent for retort in item number 3. The remaining 2 drums of clean-up manumber 12 will be liquid clean-up material and PPE)	terial in item
	2 drums @ \$1.000.00/drum	. \$2,000.00
13.	Project Management of Facility Closure by third party Includes report preparation for OH EPA	\$6,000.00
	TOTAL ESTIMATED CLOSURE COSTS	. \$73,700.00